




Fahrenheit FHT 125PRMR Power Cord Replacement

Replacing the power cord of your Fahrenheit FHT 125PRMR.

Written By: Joshua Potts



INTRODUCTION

Is the device not turning on when plug in? This guide will help you replace the power cord to fix the issue.



TOOLS:

- [iFixit Opening Tools](#) (1)
 - [Phillips #2 Screwdriver](#) (1)
 - [Phillips #1 Screwdriver](#) (1)
-

Step 1 — Power Cord



- Use your fingers or a plastic opening tool to open the side hinges on both sides of the device.

Step 2



- Using a Philips head #2 screwdriver remove the 7mm black screw from the hinge of the device.

Step 3



- Using the metal spudger, push through the hole the screw was removed from. Doing this will push the copper pin out of the other side.
- When the pin is removed the two sides of the device can now separate.
- ⓘ Be sure to collect the spring that is next to the hinge when they are separated.

Step 4



- Use the Phillips Head 1 screwdriver to remove the two screws on the back where the power cable exits the device.
- Once the two screws are removed; simply lift the case up and off to have access to the power cable.

Step 5



- To remove the power cable, grab the clear plastic holding and the base of the power cable and pull apart.

To reassemble your device, follow these instructions in reverse order.

This document was last generated on 2017-06-19 04:14:35 AM.